



# AVIATION ACTION ALERT!

Customer Support

**SUBJECT: IGNITERS WERE SHIPPED FROM FACTORY WITH INCORRECT PART NUMBER IDENTIFICATION OF CH38013.**

1. DESCRIPTION.

Champion Aerospace, Inc. has identified a limited number of igniters that were incorrectly identified and marked as CH38013 igniters and shipped for distribution.

A. Effectivity.

(1) Units Affected: CH38013 Igniters      Champion Work Order: CO30159

B. Reason.

(1) Problem/Condition.

The limited number of igniters were inadvertently marked as CH38013. The specific markings on the CH38013 igniter and the incorrectly marked igniter have the exact part markings. It includes a 5M02 date code. Figure 1, shows each igniter's dimension for ease in identifying the correct igniter.




Figure 1. Igniter Dimensions.

(2) Evidence.

Instances have been reported in service.

2. ACCOMPLISHMENT.

Champion Aerospace, Inc. will replace incorrectly identified igniters at no cost.

3. SHIPPING ADDRESS/CONTACT PERSONNEL.

Champion Aerospace, Inc.  
1230 Old Norris Road  
Liberty, SC 29657-0686 USA

Bill Austin  
Phone: (864) 843-5369  
Fax: (864) 843-5347  
E-mail: [billaustin@champaero.com](mailto:billaustin@champaero.com)