



AVIATION ACTION ALERT!

Customer Support

SUBJECT: IGNITERS WERE SHIPPED FROM FACTORY WITH INCORRECT PART NUMBER IDENTIFICATION OF CH38013

1. DESCRIPTION

Champion Aerospace, Inc. has identified a limited number of igniter's that were incorrectly identified and marked as CH38013 igniter's and shipped for distribution.

A. Effectivity

(1) Units Affected: CH38013 Igniters Champion Work Order: CO30159

B. Reason

(1) Problem/Condition

The limited number of igniter's were inadvertently marked as CH38013. The specific markings on the CH38013 igniter and the incorrectly marked igniter have the exact part markings. It includes a 5M02 date code. Figure 1, shows each igniter's dimension for ease in identifying the correct igniter.




Figure 1. Igniter dimensions

(2) Evidence

Instances have been reported in service.

2. ACCOMPLISHMENT

Champion Aerospace, Inc. will replace incorrectly identified igniter's at no cost.

3. SHIPPING ADDRESS/CONTACT PERSONNEL.

Champion Aerospace, Inc.
1230 Old Norris Road
Liberty, SC 29657-0686 USA

Bill Austin
Phone: (864) 843-5369
Fax: (864) 843-5347
E-mail: billaustin@champaero.com

20 May 03 (Rev. 1)

AA-CH38013-03-001