



Aviation Technical Bulletin

Route to:SERVICE
MANAGERSALES
MANAGERBULLETIN
BOARD*Bringing Power to Flight*

July 1998

98-3

Attention: All Distributors

Catalog Update

Please make the following changes in AV-12 catalog (*January 1998 Edition*)
immediately:

PAGE 22 Textron Lycoming IO580-A Engine with spark plug RHB37E now has FAA-PMA approval. According to the footnote the asterisk means that REM37BY can be substituted in this engine if lead fouling occurs. This is **not true** for this engine, therefore footnote should be deleted.

If you have any questions please contact your Champion Aviation representative or call 864/843-5400.