



# Aviation Action Alert

**Route to:**SERVICE  
MANAGERSALES  
MANAGERBULLETIN  
BOARD*Bringing Power to Flight*

January 1990

90-2

Champion Aviation Action Alert 89-7 requests the return of certain CH48108 and CH48109 filters (copy attached). This recall is now being expanded to include filters with affected date codes that are currently installed on engines.

You will be compensated for your labor, provided the following steps are taken:

WHEN: Immediately, or before next flight

WHAT: Remove and replace CH48108 and CH48109 oil filters displaying the following date codes which are stamped on the filter. (First three digits) 3J8, 4J8, 1K8, 2K8, 3K8, 4K8, 2L8, 1M8, 3M8.

**Reimbursement Procedures:**

1. Return affected filter to your distributor.
2. Enclose a copy of your completed work order.

You will receive a credit note from your distributor covering your labor costs up to \$40.00 (US currency) maximum per filter. Your distributor will replace the affected filter.

All distributors should contact their respective accounts to ensure all operators are notified of this Action Alert 89-7.

All claims must be approved by our Director of Sales Engineering, Jacques Beaujean, and received by March 15, 1990, to obtain compensation.

Recalled filters not installed on engines, should be returned under set guidelines in Alert Bulletin 89-7.

WLA:fcg

attachment

Please disregard bulletin AVIATION ACTION ALERT #89-7R