



Champion Aerospace LLC  
1230 Old Norris Road  
Liberty, SC/USA 29657  
Phone: (864) 843-1162 Fax: (864) 843-5471

## TECHNICAL PUBLICATION INDEX

Publication No: TPI20220101-001

Issued: Jan. 01/22

### TECHNICAL PUBLICATIONS

ABBREVIATED COMPONENTS MAINTENANCE MANUALS

COMPONENT MAINTENANCE MANUALS

OVERHAUL & INSTALLATION MANUALS

SERVICE/TECHNICAL BULLETINS

### PRODUCTS

IGNITER PLUGS

IGNITION LEADS

EXCITERS

POWER SUPPLY UNITS

### PROPRIETARY STATEMENT

The information contained in this document is proprietary property of Champion Aerospace LLC. Receipt or possession of this information does not confer, license or imply any rights to use, sell or manufacture from this information. No reproduction of publication, in whole or in part, shall be made without the express written consent of Champion Aerospace LLC. All information is covered under full protection of the United States copyright laws. Copyright ©2022, Champion Aerospace LLC. All rights reserved.

---

**IGNITER PLUGS**
**ABBREVIATED COMPONENT MAINTENANCE MANUALS**

ATA NO.	PUB. NO.	PART NUMBER	ENGINE APPLICATIONS	PUB TYPE	REV. NO.	REV. DATE
<b>GENERAL ELECTRIC</b>						
74-21-02		AA138S-4, -4B	CF6 (HARD-COPY)	ACMM	1	06/01/72
74-21-33*	501077	CH31753A	CF6-80C2	ACMM	2	09/10/13
74-21-33*		CH31687D	CFM56-2 (HARD-COPY)	ACMM	2	02/14/87
74-21-34	501081	CH31905	CF6-50, CF6-80A	ACMM	4	05/12/14
74-21-37	501079	CH31900/CH31900-6	CFM 56	ACMM	4	09/10/13
74-21-38	501074	CH31772A/CH31904-2	CF6-80E, CF6-80C2	ACMM	4	10/07/13
74-21-39	501085	CH31926	CF34-8C1	ACMM	4	07/18/14
74-21-40	501073	CH31858-1, -2	CF34-3A1, -3B, -3B1	ACMM	4	07/15/14
74-21-41*	501078	CH31843	CF6-50, CF6-80A, -A1, -A2	ACMM	2	10/07/13
74-21-46	501080	CH31965	CFM 56-3, -5, -7	ACMM	4	10/07/13
<b>HONEYWELL INTERNATIONAL</b>						
49-40-44		CH31824	GTCP 85-291, -184 (APU)	ACMM	0	08/19/02
49-40-45		CH31615	GTP 30, GTCP 30, GTCP 36 (APU)	ACMM	0	08/19/02
49-41-23		CH34731	GTCP 331-500 (B) (APU)	ACMM	0	02/08/00
49-41-24		CH31930	RE220 (RJ) (APU)	ACMM	1	07/16/03
74-21-01		CH34826-4	AS907/AS977	ACMM	1	05/02/03
<b>INTERNATIONAL AERO ENGINE</b>						
74-21-45		CH31964 (original)	IAE V2500 (No longer available)			
<b>FAA-PMA</b>						
74-21-22	503164	CH31919/CH31919-1	GE90+	ACMM	0	06/27/16
74-21-23	503190	CH34886/CH34886-1	PW500	ACMM	0	07/21/16
74-21-44	506628	CH31964-1	V2500	ACMM	0	04/24/20
74-21-84	506644	CH31991	V2500	ACMM	0	10/14/19
<b>PRATT &amp; WHITNEY CANADA</b>						
49-41-41	501083	CH34511	PW980A	ACMM	2	03/06/20
74-20-24	501432	CH34682	PW305, PW306	ACMM	2	10/07/14
74-21-08	501391	CH31918-2	PW150	ACMM	1	10/08/14
74-21-25	501434	CH34690-2	PW100	ACMM	2	10/08/14
74-21-27	501435	CH34758-2, -3	PT6C-67A, C, D	ACMM	2	10/07/14
74-21-28	501160	CH34055	PT6A, B, T, PW100, ST6L-73, -7	ACMM	1	07/29/14
74-21-29	501436	CH34723/CH34643-1	PW206, 206A, 207	ACMM	1	10/08/14

## IGNITER PLUGS (Cont'd)

## ABBREVIATED COMPONENT MAINTENANCE MANUALS

ATA NO.	PUB. NO.	PART NUMBER	ENGINE APPLICATIONS	PUB TYPE	REV. NO.	REV. DATE
74-21-30	501392	CH31929-DS	PW308A, C	ACMM	3	10/08/14
74-21-47	20180621	CH31975-2	PW308C+	ACMM	0	10/05/17
74-21-50	501162	CH34817	PW100	ACMM	1	07/29/14
74-21-51	501090	CH31955-1	PW150	ACMM	1	06/19/14
74-21-52	501382	CH31958-3	PW307	ACMM	2	11/06/17
<b>PRATT &amp; WHITNEY USA</b>						
74-20-07	502339	CH31923-5	PW4077, PW4084, PW4090	ACMM	2	05/29/15
74-21-05		AA124S-2	F-100-PW100 (HARD-COPY)	ACMM	0	06/24/74
74-21-41*		AA72S-A	PW4090, JT3C, 3D, JT4A, JT8D, JT9D	ACMM	1	02/07/02
<b>ROLLS-ROYCE</b>						
74-11-12		CH34743	RB211 535-E4, -E4B	ACMM	0	09/27/07
74-20-08		Y242-5/CH34760-1, -2	BR700, BR715, 715A1-30, B1-30, C1-30	ACMM	3	01/25/17
74-20-10		CH34879	ADOUR F405-RR-400 (HARD-COPY)	ACMM	0	08/01/89
74-20-41		YA211-25	RB211	ACMM	1	01/06/04
74-21-04		CH34736	TRENT 700, 800, RB211-524	ACMM	2	05/02/16
74-21-06		Y183-5, -6	RR/TAY 611, 620, 650	ACMM	1	01/11/17
74-21-12		CH34761	TRENT 500	ACMM	3	02/20/07
74-21-42		CH34829	TRENT 900	ACMM	0	08/29/06
74-21-53		CH34851-1	TRENT 1000	ACMM	0	02/18/09
74-21-54	501198	CH34867	RR-XWB	ACMM	0	07/17/14
74-21-70	502095	CH34747-3	RR-TRENT 900	ACMM	0	01/15/16
<b>SAFRAN POWER GROUP</b>						
49-41-07	505341	CH34889	SPU300	ACMM	0	07/02/18
<b>TURBOMECCA</b>						
74-21-15		CH34593/CH34595/CH34745	ARRIUS, ARRIEL	ACMM	1	06/25/18

**IGNITION LEADS**
**COMPONENT MAINTENANCE MANUALS**

ATA NO.	PUB. NO.	PART NUMBER	ENGINE APPLICATIONS	PUB TYPE	REV. NO.	REV. DATE
<b>GENERAL ELECTRIC</b>						
74-20-30		CH53552-DS	CFM 56-3B1, 2	CMM	2	03/10/08
74-20-40		CH53552-DS	CFM 56-3C1	ACMM	1	03/10/08
<b>HONEYWELL INTERNATIONAL</b>						
50160		50160-1 THRU -60	GTCP 36-, -85 SERIES, TSCP 700 (HARD-COPY)	OH W/IPL	0	07/08/88
53051		50221-1 THRU -33 (OH)	TPE 331, TFE 731 SERIES (HARD-COPY)	OH W/IPL	0	05/04/80
49-41-15		53331-DS	GTCP 331-350C, GTCP331-500 (APU)	CMM	3	07/18/06
49-41-19	506109	53179-DS (-1 THRU -17)	GTCP 36-208B, GTCP 36-300 (APU)	CMM	7	09/10/19
49-41-20		CH53540-2	GTCP 331-600 (APU)	CMM	0	04/02/02
49-41-26		CH53488-DS	RE 220 (RJ) (APU)	CMM	0	10/01/00
49-41-29		53348-DS	RE 220 (APU)	CMM	0	07/16/99
74-20-14		CH53323-DS	CFE 738	CMM	1	09/22/99
74-20-15		CH53542-DS	HTF (AS907)	CMM	2	03/29/11
74-22-01		53214/53215/53282/53283	ALF 502, LF 507 SERIES (HARD-COPY)	CMM	0	01/18/91
<b>INTERNATIONAL AERO ENGINE</b>						
74-20-45		CH53564, -1	IAE V2500	CMM	1	10/10/17
<b>FAA-PMA</b>						
74-20-46		CH53566-DS	CF6-45, -50, -80A, -80C2, -80E/E1	CMM	2	04/28/09
74-20-48		CH53515-DS	CF34-3, -8	CMM	5	06/21/18
74-20-49		CH53569-DS	CFM56	CMM	3	03/01/19
74-20-50		CH53440, -1	CFM 56-7	CMM	2	03/13/16
<b>PRATT &amp; WHITNEY CANADA</b>						
49-40-01	501153	50383-J, -K, -L	PT6B, PW100, PW901A (APU)	CMM	5	06/19/14
49-41-10		CH53611-1_-9	APS3200	ACMM	0	PENDING
49-41-43		CH53567	PW980A	CMM	1	11/28/06
74-20-02	501451	CH53399-DS	PT6A, B, T, T400	CMM	3	04/08/15
74-20-05	502393	53367-01	PW100	CMM	2	07/30/14
74-20-06		53067-21, -38.5	JT15D	CMM	2	04/24/03
74-20-09	501157	CH53456-2	PW150	CMM	3	07/16/14
74-20-11	502394	53300-DS	JT15D	CMM	4	10/23/15
74-20-12		CH53463	PT6B-36A, -36B	CMM	0	11/28/99

**IGNITION LEADS (CONTINUED)****COMPONENT MAINTENANCE MANUALS**

ATA NO.	PUB. NO.	PART NUMBER	ENGINE APPLICATIONS	PUB TYPE	REV. NO.	REV. DATE
74-20-19		53402-DS	PT6	CMM	0	02/15/99
74-20-20	502395	53335-01	PW100 SERIES	CMM	3	03/10/16
74-20-21		CH53238-1	PW305A, PW306A, B, C	CMM	2	07/17/03
74-20-22	501973	CH53442-DS/CH53450	PW206A, B2, C, D, PW207C, D, K	CMM	4	04/08/15
74-20-23	501975	CH53470-DS	PT6A-68, -68B, -68C	CMM	5	04/08/15
74-20-25	501976	CH53471-1	PT6C-67B	CMM	1	04/08/15
74-20-26	501089	CH53483-05, -06, -07	PW308A, C	CMM	2	06/23/14
74-20-27	501974	CH53529/CH53490	PT6C-67A, C, D	CMM	2	04/08/15
74-20-29	501156	CH53536-1	PW150	CMM	2	06/23/14
74-20-31	CH53544-1	CH53544-1	PW307A	CMM	2	11/06/17
74-20-35		53287	PW206	CMM	0	03/30/99
74-20-57	20180621	CH53590	PW308C+	CMM	0	09/14/17
74-20-59	20180621	CH53622-1, -2	PT6C-67A	CMM	0	02/12/18

**PRATT & WHITNEY USA**

74-20-32		CH53551-1	PW4000	CMM	1	05/17/05
74-20-44		CH53556	PW2000	CMM	0	07/27/05
74-20-47		CH53568-DS	PW/JT8D	CMM	0	10/17/07

**ROLLS-ROYCE**

74-20-42		CH53538-4	TRENT 900 (ROSEMOUNT)	CMM	0	09/05/06
74-20-43		CH53557-DS	AE3007	CMM	0	02/06/07
74-20-52	502046	CH53571, -2	TRENT 1000, TRENT 1000-TEN	CMM	1	03/01/15
74-20-53	502953	CH53571-1	RR-XWB	CMM	0	07/24/15
74-20-82		CH53538-4	TRENT 900	ACMM	0	01/22/08

**SAFRAN POWER GROUP**

49-41-08	505340	CH53616-DS	SPU300	CMM	0	07/25/18
----------	--------	------------	--------	-----	---	----------

**TURBOMECCA**

49-40-02		53267-3, -4	APS2000 (APU)	CMM	0	12/02/94
----------	--	-------------	---------------	-----	---	----------

## EXCITERS

## COMPONENT MAINTENANCE MANUALS

ATA NO.	PUB. NO.	PART NUMBER	ENGINE APPLICATIONS	PUB TYPE	REV. NO.	REV. DATE
<b>HONEYWELL INTERNATIONAL</b>						
49-41-01	501140	CH92036	131-9A, B	CMM	3	11/16/15
49-41-02	501146	CH92125	131-9A, B	CMM	1	09/18/15
49-41-11		CH92131	HGT1700	ACMM	0	PENDING
74-11-06	501141	CH92074-6	HTF 7000	CMM	3	02/01/14
<b>FAA-PMA</b>						
74-11-20	N/A	CH92133	RR M250	CMM	0	07/05/16
74-11-49	500836	CH92100	CF6, CF34, CFM56, GE90	ACMM	4	03/05/14
<b>PRATT &amp; WHITNEY CANADA</b>						
74-11-01	N/A	CH92028	JT15D-1, -1A, -1B, -4, -4B, -4D, -5, -5A	CMM	1	01/29/11
74-11-03	N/A	CH92015, -1	*** Obsolete *** (See 74-11-05)	-	-	-
74-11-04	502190	CH92043-DS	PW150	CMM	8	06/09/15
74-11-05	507053	CH92015DS_CH92106DS	PW206, PW207, PT6A, PT6C, PT6B	CMM	5	12/15/20
74-11-08	507701	CH92051-2, -3, -4, -5	PW308C	CMM	4	04/05/21
74-11-09	507431	CH92083-3, -4, -5, -6, -7	PW307A	CMM	4	03/11/21
74-11-10	507700	CH92090-1, -2, -3	PW308A	CMM	2	06/2/21
<b>ROLLS-ROYCE</b>						
74-11-11*	501452	CH92077	TRENT 900	CMM	1	01/15/15
74-11-11	N/A	CH92077	***Obsolete*** (See 74-11-11)	ACMM	0	08/31/08
71-11-51	507350	CH92095-4	TRENT 1000	CMM	3	08/07/19
74-11-55	502931	CH92107-5	RR-XWB	CMM	0	10/01/14
<b>SAFRAN POWER GROUP</b>						
49-41-03	505339	CH92135-3	SPU300	CMM	0	02/19/18
<b>WILLIAMS INTERNATIONAL</b>						
74-11-17	502438	CH92007-1	FJ-44	CMM	0	04/01/15
74-11-21		CH92147	FJ-33	ACMM	0	PENDING
<b>INSTALLATION/OPERATION GUIDES</b>						
N/A	501336	305136	INDUSTRIAL APPLICATION (CSA)	I/OG	5	03/30/17
N/A	501340	CH92022	INDUSTRIAL APPLICATION	I/OG	2	08/26/14
N/A	501341	CH92099	INDUSTRIAL APPLICATION (ATEX)	I/OG	1	08/26/14

**EXCITERS (CONTINUED)****COMPONENT MAINTENANCE MANUALS**

ATA NO.	PUB. NO.	PART NUMBER	ENGINE APPLICATIONS	PUB TYPE	REV. NO.	REV. DATE
N/A	501342	CH92112	INDUSTRIAL APPLICATION	I/OG	1	07/24/14
NA	507561	CH92154	INDUSTRIAL APPLICATION	I/OG	1	08/27/21

**POWER SUPPLY UNITS****ABBREVIATED COMPONENT MAINTENANCE MANUALS**

ATA NO.	PUB. NO.	PART NUMBER	ENGINE APPLICATIONS	PUB TYPE	REV. NO.	REV. DATE
24-31-04		28VS50Y	VARIOUS	CMM	2	02/02/93
24-31-01*		28VS200Y-26	VARIOS (HARD-COPY)	CMM	0	07/01/88
24-31-03*	502368	28VS100Y-10A, -10B, -10C	VARIOUS (SCAN)	CMM	9	08/24/15
24-31-03*		28VS100Y-17	VARIOUS	CMM	0	04/01/88
24-31-46	502096	28VS200Y-4DH	DEHAVILLAND	CMM	5	10/12/18
24-32-11	501166	28VS200Y-4B, 4B-1, 4B-2	BOEING	CMM	7	05/16/14
24-1-1*		28VS50C	VARIOUS (HARD-COPY)	OH	0	03/01/64
24-1-1*		28VS50C-3	VARIOUS (HARD-COPY)	OH	0	07/01/63
24-1-1*		28VS200Y-17	GULFSTREAM II	OH	2	01/29/10
24-31-07		28VS100Y-19	VARIOUS (HARD-COPY)	IPL	0	03/27/01
24-31-01*		28VS200Y-13	VARIOUS (HARD-COPY)	OH	0	04/05/00
2981780		28VS200Y-4A to -4D	VARIOUS	CP	0	06/24/94
N/A		28VS200Y-4DH	VARIOUS	CFRP	0	12/11/03
N/A		28VS120Y-1, -2, -3, -5	VARIOUS	IPD	2	04/10/08
N/A		28VS200Y-32	VARIOUS	T/IPD	0	02/01/08

**ACTION ALERTS****ACTION ALERTS/SERVICE BULLETINS/SERVICE LETTERS/TECHNICAL BULLETINS**

YEAR	ISSUE NO.	DESCRIPTION	ISSUE DATE
2003	A.A.CH38013-03-001	CH38013 Incorrect P/N Identification	05/03
2000	00-1	Oil Filter Base (Adaptor)	01/00
	00-2	CF0100 & CF0101 Oil	12/00
1998	98-1AA	Stop Using DC-200 & DC-4	03/98
	98-2AA	28VS100Y-10B Loose AC Filter Capacitor Condition	12/98
1997	97-1	Harness Applications	07/97
	97-2	Inspection of Oil Filters	07/97
	97-3AA	CH31815/CH31621 Igniter Plug	12/97
1994	94-1	Engines Operated On Contaminated Fuels	08/94
1993	93-1	CH34055 and CH34406 Igniter Inspection	11/93
1991	91-1	Oil Filters CH48108 and CH48109	11/91
1990	90-2	Oil Filters CH48108 and CH48109 Recall Expanded	01/90
1989	89-1	General Electric CFM56-5 Engines	02/89
	89-7/89-7R	Oil Filters CH48108 and CH48109 Recall	12/89
1988	88-2	FHE164E Igniter Recall	03/88
	88-4	AA72S Igniter Recall	09/88
1986	86-1	"CHAMP" Brand Oil Filters	09/86

**SERVICE BULLETINS**

YEAR	ISSUE NO.	DESCRIPTION	ISSUE DATE
2021	S.B.CH92083-74-003	Exciter Replacement Upgrade to -7	03/21
	S.B.CH92051-74-003	Exciter Replacement Upgrade to -5	06/21
	S.B.CH92090-74-002	Exciter Replacement Upgrade to -3	06/21
	S.B.CH92142-74-001	Exciter Replacement Upgrade to New Model	11/21
2020	S.B.CH92106-74-003	Exciter Replacement Upgrade to -4. -5	12/20
2019	S.B.CH31990-74-001	Replacement of V2500 TurboFan Engine Igniter Plug	07/19
	S.B.CH31991-74-001	Replacement of V2500 TurboFan Engine Igniter Plug	08/19
2018	S.B.CH92106-74-002	Exciter Replacement Upgrade to -2, -3	11/18
2017	S.B.CH31964-1-74-001	Igniter Replacement From No Dash to -1	03/17
2012	S.B.CH31964-74-21-001	Igniter Plug Introduction	05/12
2011	S.B.CH92074-74-001	Exciter Replacement (PPT to SPIDER)	05/11
2010	S.B.CH92043-74-001	Exciter Replacement (PPT to SPIDER)	02/10
	S.B.CH92090-74-001	Exciter Replacement (PPT to SPIDER)	04/10



<b>SERVICE BULLETINS (CONTINUED) ACTION ALERTS/SERVICE BULLETINS/SERVICE LETTERS/TECHNICAL BULLETINS</b>			
<b>YEAR</b>	<b>ISSUE NO.</b>	<b>DESCRIPTION</b>	<b>ISSUE DATE</b>
<b>2009</b>	S.B.CH92051-74-001	Exciter Replacement Upgrade From -2 to -3	05/09
	S.B.CH92051-74-002	Exciter Replacement Upgrade From -3 to -4	05/09
	S.B.CH92083-74-001	Exciter Replacement Upgrade From -4 to -5	02/09
	S.B.CH92083-74-002	Exciter Replacement Upgrade From -5 to -6	02/09
	S.B.CH92106-74-001	Exciter Replacement, Replaces CH92015, -1 Models	08/09
<b>2008</b>	S.B.CH53536-1-74-001	Ignition Lead Replacement	12/08
<b>2002</b>	S.B.CH34817-21-02-001	CH34817 Igniter Cleaning, Inspection and Testing	07/02
	S.B.CH92036-49-41-001	CH92036 Exciter, Tank Capacitor Upgrade	01/02
	S.B.CH92036-49-41-001-R1	CH92036 Exciter, Tank Capacitor Upgrade, Rev. 1	02/02
<b>1999</b>	S.B.MS17976-2-24-001	28VS100Y-10A, -10B, -10C TRU AC Filter Capacitor Inspection	05/99
<b>1989</b>	S.B.28VS200Y-4B-24-4	Install New DC Terminal Hardware	01/89
<b>1987</b>	S.B.28VS200Y-4B-24-5	Install New DC Terminal Hardware	01/87
<b>SERVICE LETTERS</b>			
<b>YEAR</b>	<b>ISSUE NO.</b>	<b>DESCRIPTION</b>	<b>ISSUE DATE</b>
<b>2014</b>	S.L.CH31964-74-21-001	Serviceability Limits	10/14
<b>2013</b>	S.L.74-21-001	Spark Plug Resistance Values	03/12
<b>2011</b>	S.L.74-10-001	Tomado Ally Turbo TAT SB11-05	09/11
<b>2007</b>	S.L.06-07-001	Oil Filter Recommended "Use By" Date	06/07
<b>2004</b>	S.L.28VS200Y-4DH-24-04-001	Fan Motor Upgrade	01/04
	S.L.28VS200Y-4DH-24-04-001-R1	Fan Motor Upgrade.	07/04
<b>2000</b>	S.L.MS17976-2-24-003	28VS100Y-10A, -10B TRU Fan Motor Upgrade	08/00
<b>TECHNICAL BULLETINS</b>			
<b>YEAR</b>	<b>ISSUE NO.</b>	<b>DESCRIPTION</b>	<b>ISSUE DATE</b>
<b>2019</b>	19-001	CH38013 Igniter Plug	04/19
<b>2016</b>	16-001	Servicing Iridium Fine Wire Spark Plug	02/16
<b>2015</b>	15-001	Servicing Iridium Fine Wire Spark Plug	12/15
<b>2014</b>	T.B.F135-14-001	CH31960-2 Igniter Plug	03/14
	T.B.F135-14-002	CH31959-1 Igniter Plug	03/14
	T.B.F135-14-003	CH53548, CH53554, CH53555 High Tension Leads	03/14
<b>2007</b>	T.B.CH31921-07-001	CH31921 Igniter Plug	03/07
	T.B.CH31858-2-07-002-R1	CH31858-2 Igniter Plug	05/07
<b>2004</b>	T.B.CH92040-1-04-001	CH92040-1 Exciter Modification/Repair	07/04
	T.B.CH92043-2-02-002-R2	CH92043-1 Upgrade to CH92043-2, Rev 2	02/04

**TECHNICAL BULLETINS (CONTINUED) ACTION ALERTS/SERVICE BULLETINS/SERVICE LETTERS/TECHNICAL BULLETINS**

YEAR	ISSUE NO.	DESCRIPTION	ISSUE DATE
2003	T.B.CH34739-74-20-03-001	CH34739 Igniter, Cleaning, Inspecting, Testing	10/03
	T.B.CH92043-2-02-002-R1	CH92043-1 Upgrade to CH92043-2, Rev 1	08/03
2002	T.B.CH92043-1-02-001	CH92043 Upgrade to CH92043-1	02/02
	T.B.CH92043-2-02-002	CH92043-1 Upgrade to CH92043-2	09/02
	T.B.CH34682-74-20-02-003	CH34682 Igniter, Inspection/Check Instructions	10/02
2001	01-2	CH31876-6 Igniter Plug	05/01
	01-3	Spin-On Oil Filter	05/01
	01-4	Continuous Improvement Champion Oil Filters	05/01
2000	00-1	Oil Filter Base (Adapter) & Oil Filter Inspection	01/00
	00-4	Champion Spin-On Oil Filter	11/00
1999	99-1	Champion Igniter CH34690-2 Cleaning, Inspection and Testing	03/99
	99-2	Spark Plug Installation	10/99
1998	98-1	Discontinue use of DC200 and DC4 Lubricants	03/98
	98-1AL	Champion Y183-5 Igniter Plug	02/98
	98-2	Champion CH34016-1 Igniter Plug	05/98
	98-2AL	Champion Y183-6 Igniter Plug	02/98
	98-3	Catalog Update	07/98
	98-6	Champion FHE164E Igniter Plug	12/98
	98-7	Warning! Never Brush or Grind Spark Plugs Electrodes	12/98
1997	97-1	All JT15D Operators Exciter 305013 Changed to CH92028	01/97
	97-2	Champion CH37114 Igniter Plug	01/97
	97-3	Champion CH31815-1 Igniter Plug	02/97
	97-4	AV12-H Harness Application Chart Additions/Corrections	03/97
	97-6	Turbine Lead Connector Wear Gauge CT497	12/97
	97-7	Calibrated Wear Gauge CT496	12/97
	97-8	CAP Recip Harnesses	12/97
	97-9	Harness Routing	12/97
1996	96-1	CH38016 Igniter	07/96
	96-1AL	Champion CH34549 Igniter Plug	03/96
	96-2	Champion CH34659-3 Igniter Plug	10/96
	96-2AL	How Long Should An Igniter Last?	09/96
	96-4	Continuous Improvements...Champion Aviation Oil Filters	11/96
1995	95-1	Champion CH31824 Igniter Plug	03/95
	95-2	Rolls-Royce Trent, RB211 Series CH34698 Igniter	05/95

**TECHNICAL BULLETINS (CONTINUED) ACTION ALERTS/SERVICE BULLETINS/SERVICE LETTERS/TECHNICAL BULLETINS**

YEAR	ISSUE NO.	DESCRIPTION	ISSUE DATE
	95-3	Champion CH34313 Igniter Plug	06/95
	95-3	Reliability Exciter FJ44-1A Exciter	08/95
	95-4	Champion CH31801 Igniter Plug	06/95
	95-5	Oil Filter Application	08/95
	95-6	Champion CH34687A Igniter Plug	08/95
	95-7	Champion AA134S-1 Igniter Plug	11/95
	95-9	"Let's Illuminate"	11/95
	95-10	"How Long Should Spark Plugs Last?"	11/95
	95-11	Aviation Spark Plugs - Always Install With New Gasket	11/95
	95-12	Champion CH31801 Igniter Plug	11/95
	95-13	Spark Plug Re-Gapping Procedure	11/95
	95-14	Reconditioned Spark Plug & Turbine Igniter Identification	11/95
	95-15	Normal vs. Abnormal Semi-Conductor Wear	11/95
<b>1994</b>	94-1	Champion CH34803 Series 21 Igniter Plug	03/94
	94-2	Inspect Oil Filters	12/94
	94-3	Once You Remove It, Tear It Apart	12/94
<b>1993</b>	93-1	Champion CH31876 Igniter Plug	04/93
	93-2	Servicing The Iridium "S" Plug	04/93
	93-3	Champion CH34419 Igniter Plug	04/93
	93-4	Do Not Overtorque Oil Filters	04/93
	93-5	Beware Of Reconditioned Spark Plugs	04/93
	93-7	Champion CH31815 Igniter Plug	12/93
	93-8	Using The Model 2600A Vibrator	12/93
	93-9	If The Plug Fails The CT-482 Test, Scrap It	12/93
<b>1991</b>	91-3	Lycoming Service Instruction #1442	03/91
	91-4	Champion CH31723 Igniter Plug	07/91
<b>1990</b>	90-2	CH31547C Igniter Inspection	05/90
	90-3	Champion CH34484 Igniter Plug	07/90
	90-4	Applying Anti-Seize	09/90
	90-5	Gaskets Filter	09/90
<b>1989</b>	89-1	Follow Engine Manufacturers' Cold Starting Procedure	03/89
	89-2	Attention All TPE331 Operators-Garrett Lowers Installation Torque	03/89
	89-3	Turbine Ignition Leads "Handle With Care"	05/89
	89-4	Turbine Lead Inspection Lead	05/89

**TECHNICAL BULLETINS (CONTINUED) ACTION ALERTS/SERVICE BULLETINS/SERVICE LETTERS/TECHNICAL BULLETINS**

YEAR	ISSUE NO.	DESCRIPTION	ISSUE DATE
	89-5	Connector Weld Flashover	05/89
	89-6	Champion CH34511 Igniter Plug	08/89
<b>1988</b>	88-1	#533 Abrasive Replaced By 91893	01/88
<b>1987</b>	87-1	REM37BY Electrode Wear	02/87
	87-4	Proper Use of The CT-470 Can Cutter	03/87
	87-5	If Your Turbine Engine Is Ready For Overhaul, So Are Your Ignition Leads	04/87
	87-6	Check These Dimensions	05/87
	87-8	Always Install Igniters With New Gaskets	07/87
	87-9	Announcing The Champion CT-494 Igniter Erosion Gage	07/87
	87-10	Champion CH34406 Igniter Plug	08/87
	87-11	Oil Filter Application TSIO 520BE	11/87
<b>1986</b>	86-1	Champion CH31753A/CH31772 Igniter Plug	02/86
	86-11	Champion CH31769 Igniter Plug	06/86
	86-12	Champion FS109-1A Igniter Plug	08/86
	86-13	Champion Spin-On Filters With OF712 Installation	08/86
	86-15	Use Correct Filter With CH48922 Filter	09/86
	86-17	Champion CH34055 Igniter Plug	11/86
<b>1985</b>	85-1	Champion CH31547C Igniter Plug	01/85
	85-2	Champion CH34249 Igniter Plug	02/85
	85-3	Champion AA33SD Igniter Plug	02/85
	85-4	Champion CH34279B Igniter Plug	02/85
	85-5	PT-6 Igniter Gaskets Igniter Plug	04/85
	85-6	Champion CH31701A Igniter Plug	04/85
	85-7A	Champion CH31765 Igniter Plug	05/85
	85-12	Champion CH34206C Igniter Plug	08/85
	85-13	CT-475AV Tester Calibration	08/85
	85-13A	Champion CH34208 Igniter Plug	09/85
	85-16	Iridium VS Platinum It's A Matter of Economics	11/85
<b>1984</b>	84-1	Champion CH31615 Igniter Plug	01/84
	84-2	Frequent Oil & Oil Filter Changes Minimize Oil Contamination	02/84
	84-5	Cross Reference Chart Replacement Parts Model CT-475AV	05/84
	84-6	Champion FHE246-4 Igniter Plug	05/84
	84-10	Champion CH31687/CH31706 Igniters	12/84
<b>1983</b>	83-1	Champion CH37103 Igniter Plug	01/83

**TECHNICAL BULLETINS (CONTINUED) ACTION ALERTS/SERVICE BULLETINS/SERVICE LETTERS/TECHNICAL BULLETINS**

YEAR	ISSUE NO.	DESCRIPTION	ISSUE DATE
	83-2	CH34177 Igniter Plug	04/83
	83-3	Constant Polarity Wear/Excessive Electrode Erosion	04/83
	83-4	Champion FHE267-2A Igniter Plug	04/83
	83-8	Champion FHE113-10 Igniter Plug	06/83
	83-9	Oil Filter Inspections	11/83
<b>1982</b>	82-3	Champion CH31621 Igniter Plug	06/82
	82-4	Champion CH34157B Igniter Plug	08/82
	82-5	Champion CH34187 Igniter Plug	08/82
	82-6	CT-475AV Trouble Shooting Method	09/82
	82-8	Champion FS47 Igniter Service Instruction	11/82
	82-9	Champion CH34016 Igniter Plug	11/82
	82-11	Champion CH34135 Igniter Plug	11/82
<b>1981</b>	81-3	Regapping The New REM37BY	01/81
<b>1980</b>	80-1	Champion CH34168 Igniter Plug	02/80
<b>1979</b>	79-1	Abrasive Compound Use	01/79
	79-2	Champion FHE211-2 Igniter Plug	04/79
	79-3	Champion CH34084 Igniter Plug	05/79
<b>1978</b>	78-1	Equivalent Oil Filter Part Numbers	02/78
	78-2	Know Your Oil Filters	03/78
	78-4	Champion FHE161-9 Igniter Plug	06/78
<b>1977</b>	77-3	Champion FHE-151 Igniter Plug	04/77
	77-4	Remember...Two Wrongs Don't Make A Right	06/77
	77-5	Get The Lead Out - Faster	09/77
	77-7	Champion Has The Oil Filter For Cessna's New 152 Trainer	10/77
	77-8	Champion Plug For The New Cessna 152 Trainer	11/77
<b>1976</b>	76-2	Champion AA136S Igniter Plug	02/76
	76-3	Champion FHE-146 Igniter Plug	03/76
	76-4	Check These Dimensions	04/76
	76-5	Are Your Using The Proper Gasket	04/76
	76-8	Constant Spark Plug Electrode Polarity Wear	09/76
	76-9	Champion FHE 267-2 Igniter Plug	10/76
<b>1975</b>	75-1	The Model 2400 Dry Abrasive Cleaner	01/75
	75-4	Champion Spin—On Filters For Duke And Baron Operators	05/75
	75-6	Spin-On Filter Sticking	07/75

**TECHNICAL BULLETINS (CONTINUED) ACTION ALERTS/SERVICE BULLETINS/SERVICE LETTERS/TECHNICAL BULLETINS**

YEAR	ISSUE NO.	DESCRIPTION	ISSUE DATE
	75-7	Champion FHE-182 Igniter Plug	08/75
	75-8	To Scrap Or Not To Scrap	10/75
<b>1974</b>	74-1	Champion FS118 Igniter Plug	01/74
	74-2	80 Octane Operators	02/74
	74-3	Champion FHE-19 Dart Igniter Plug	04/74
	74-4A	Champion FS 93 Igniter Service Instructions	05/74
	74-5	Help Prevent Lead Fouling	06/74
	74-6A	Champion FHE-176 Igniter Plug	07/74
	74-7	Model 200 Vibrator Cleaner Service Parts	09/74
	74-8	Champion FHE-246 Igniter Plug	11/74
<b>1973</b>	73-1	AGF2 Glow Plug	01/73
	73-2	Is Your Cleaner Doing The Job For You?	02/73
	73-3	New & Different Spark Plugs For New & Different Engine	03/73
	73-4	Champion FHE-205 Igniter Plugs	04/73
	73-8	New or Used Aviation Spark Plugs - Always Install With A New Gasket	08/73
	73-9	"If It's Been Dropped Once, Drop It Again"	09/73
	73-10	Hard Starting	10/73
	73-11	FAA Cautions Pilots On Using Automotive Gasoline In Aircraft	11/73
<b>1972</b>	72-2	Murphy's Law - Improper Spark Plug Installation	02/72
	72-3	Iridium Precious Metal - Handle With Care	03/72
	72-6	Oil Filter Systems	06/72
	72-7	Too Small A Gap Is As Bad As Too A Large	07/72
	72-8	Used Spark Plugs Better Than New? Never!	08/72
	72-9	Spark Plug Testers Need Testing, Also!	09/72
	72-10	Spark Plug Testing - Why & How	10/72
<b>1971</b>	71-2A	JT9 Igniter Wear Characteristics	01/71
	71-5	It's A Matter of Economics	04/71
	71-6	AV-Gas, Tetraethyl Lead (TEL) & Spark Plugs	05/71
	71-7	Spark Plug Cleaners Need Cleaning Also	06/71
	71-8	Just Because It Looks Good, "Change It" Anyway	07/71
	71-9	Short Plug Life??	08/71
	71-10	Proper Torquing Can Assure Against Oil Filter Leaks	09/71
	71-11	Oil Filter Assembly Needs Cleaning Too	10/71

**TECHNICAL BULLETINS (CONTINUED) ACTION ALERTS/SERVICE BULLETINS/SERVICE LETTERS/TECHNICAL BULLETINS**

YEAR	ISSUE NO.	DESCRIPTION	ISSUE DATE
	71-12	With or Without a Turbo Charger, Just A Reminder	11/71
<b>1970</b>	70-2	Fine Wire Spark Plugs, To Clean or Not to Clean - That is the Question	03/70
	70-3	DC-4 or DC-200 Compound Recommended To Prevent Connector Grommets From Sticking	04/70
	70-4	Top Spark Plugs To Bottom...Bottom Spark Plugs To The Top	05/70
	70-5	Summer Is Here! General Service	06/70
	70-8	Capacitance	09/70
	70-9	Swap Spark Plug Location To Equalize Wear	10/70
	70-10	Slow Death On A Fast Wheel	11/70
<b>1969</b>	69-1	How Bad Is One Plug Out?	03/69
	69-2	Know These Engine Combustion Conditions?	02/69
	69-3	Let's Inject	03/69
	69-5	Have You Got The Right Pitch	04/69
	69-7	AGF2-5 Igniter Life PT6 Engine	05/69
	69-8	Cracking Insulator Ceramics?	07/69
	69-9	Go The Step Beyond	08/69
	69-10	There Are Spark Plug Copy-Cats	11/69
	69-11	Testing 1-2-3-4 Testing	12/69
<b>1968</b>	68-1	Hard Starting	01/68
	68-3	Spark Plug Testing - Why & How	02/68
	68-7	How's Your Oil Consumption	03/68
	68-8	Old Spark Plugs Better Than New Ones? Never!	06/68
	68-9	The Whole Job	07/68
	68-10	To Clean Or Not Too Clean	07/68
	68-11	What Is A Nominal Gap?	08/68
	68-12	Swap Your Troubles Away	08/68
	68-14	The Pilot and Plug Fouling	09/68
	68-15	How's Your Timing - Magneto, That It?	10/68
	68-16	Gap Settings For J43 & REJ38 Spark Plugs	10/68
	68-17	Short Plug Life??	11/68
<b>1967</b>	67-1	Champion AA Series PW Igniters Firing End Wear Limit Measurement	02/67
	67-2	Gap Bridging On Fine Wire Plugs	05/67
	67-3	Used Spark Plug Gaskets	07/67
	67-4	Fouling On Continental I0-520 Engine	08/67
	67-5	Throttle Jockeying	09/67

**TECHNICAL BULLETINS (CONTINUED) ACTION ALERTS/SERVICE BULLETINS/SERVICE LETTERS/TECHNICAL BULLETINS**

YEAR	ISSUE NO.	DESCRIPTION	ISSUE DATE
	67-6	Dust Fouls Engines & Spark Plugs	10/67
	67-7	Is Your Champion Cleaner Doing A Good Job?	10/67
	67-8	Do You Use A Looking Glass?	11/67
	67-9	If It Looks Dirty, Leave It Alone	11/67
	67-10	EGT and Spark Plugs	12/67
	67-11	Improper Gaps From Gapping Tools	12/67
<b>1965</b>	65-1	REL37B Approval	04/65
	65-2	Discontinued 700-E Series Service Unit	06/67
<b>1963</b>	63-1	Champion Spark Plugs RHB36P & RHB 38E Approvals	11/63
<b>1962</b>	62-1	Removal of Semi-Conductor From FHE-100-X6 Igniters	07/62
	62-2	Servicing of Champion Platinum Electrode Spark Plugs	08/62
<b>1961</b>	61-1	Spark Plug Thermocouple - Variation In Head Temperature Indication	02/61
	61-2	Champion AA15S & AA16S Igniter plugs	10/61
	61-3	Instructions For Use of Champion CT-429 Torque Limiter	10/61
<b>1960</b>	60-1	Center Electrode Copper Erosion	07/60
	62-3	Champion FHE-19-6H (CR-104) Inspection and Reconditioning Procedure	11/62
	60-2	New Spark Plug Cleaner Accessories	09/60