



AVIATION TECHNICAL BULLETIN

Champion Spark Plug Company

P. O. BOX 910, TOLEDO, OHIO 43601


ROUTE TO	
SERVICE MANAGER	
SALES MANAGER	
BULLETIN BOARD	

April 5, 1976

NO. 76-4

CHECK THESE DIMENSIONS...

WHEN INSTALLING SPIN-ON TYPE OIL FILTERS, REGARDLESS OF MAKE OR MANUFACTURE, ALWAYS CHECK THE ENGINE OIL FILTER ADAPTER STUD FOR SECURITY AND MINIMUM DIMENSIONAL PROTRUSION AS ILLUSTRATED BELOW:



IF THIS DIMENSION IS BELOW REFERENCED MINIMUM, REMOVE THE FILTER ADAPTER FROM THE ENGINE AND INSPECT FOR CAUSE OF TROUBLE AND CORRECT AS NEEDED.
