



# Aviation Technical Bulletin

**Route to:**SERVICE  
MANAGERSALES  
MANAGERBULLETIN  
BOARD*Bringing Power to Flight®*

November 1995

95-13

*Revised 95-8*

## SPARK PLUG RE-GAPPING PROCEDURE

Recent reports received in this office confirm Champion spark plug gap setting tools can be damaged by attempting to re-set gaps on some other brands of two ground electrode massive plugs.

Generally, the adjustment screw and knob assembly on the small tool (P/N CT-415AV) and the toggle arm on the large tool (P/N 2500A) will be damaged.

Replacement parts are as follows:

CT-415AV Screw and Knob	Order P/N GT-207
Model 2500A Toggle Arm	Order P/N CT-458-4

Please keep in mind, all Champion gapping tools were designed to re-gap Champion Aviation spark plugs only.