



Bringing Power to Flight®

Aviation Technical Bulletin

Route to:

SERVICE
MANAGER

SALES
MANAGER

BULLETIN
BOARD

JULY 1998

98-3

ATTENTION: ALL DISTRIBUTORS

CATALOG UPDATE

Please make the following changes in AV-12 catalog (*January 1998 Edition*) immediately:

PAGE 22 Textron Lycoming IO580-A Engine with spark plug RHB37E now has FAA-PMA approval. According to the footnote the asterisk means that the REM37BY can be substituted in this engine if lead fouling occurs. This is **not true** for this engine, therefore footnote should be deleted.

If you have any questions please contact your Champion Aviation representative or call 864/843-5400.

Champion Aviation Products: Your Blueprint for Performance