



AVIATION TECHNICAL BULLETIN

Champion Spark Plug Company

P. O. BOX 910, TOLEDO 1, OHIO • U. S. A.

June 30, 1965

NO. 65-2

CONTROLLED
COPY

700-E SERIES SERVICE UNIT

Repair parts for the 700-E Series Service Unit will no longer be stocked after present supply is exhausted.

Manufacture of this unit ceased in 1957, and we have now fulfilled our obligation of handling repair parts for a period of seven years. This is in line with the industry standard on discontinued items.

CHAMPION SPARK PLUG COMPANY

R. L. Anderson
Aviation Service Manager

RLA:ss