



# AVIATION TECHNICAL BULLETIN

Champion Spark Plug Company

P. O. BOX 910, TOLEDO, OHIO 43601

December 4, 1967

NO.

67-11

CONTROLLED  
COPY

## WARNING!

### IMPROPER GAPS FROM GAPPING TOOLS

Improper use of certain gapping tools results in very narrow gap settings.

It is important, therefore, that all gaps be checked with a wire gauge after gap settings to assure that the setting obtained is equal to that desired.

Excessively narrow gaps can cause engine roughness and consequent pilot concern. Check the electrode gaps on all plugs before installation -- especially if plugs have been serviced in any way.

\*\*\*

*first choice for dependable engine performance*