



AVIATION TECHNICAL BULLETIN


Champion Spark Plug Company

P. O. BOX 910, TOLEDO, OHIO 43601

August 1, 1967

NO. 67-4
CONTROLLED
COPY

HAVING SPARK PLUG FOULING IN YOUR CONTINENTAL 10-520 ENGINE?



MODEL 10-520
6 cyl., 520 cu. in. disp.
285 hp @ 2700 rpm

Then may we suggest you try the CHAMPION RHB32E Spark Plug.

Many operators are reporting excellent results after changing to the RHB32E plug. The plugs are readily available through your local Champion supplier.

Note: This plug replaces the RHB32N and RHB33E spark plugs and is approved wherever they have been approved. Of course, the fine-wire spark plugs RHB32P and RHB32W are also approved in this engine.

CHAMPION SPARK PLUG COMPANY

R. L. Anderson
Aviation Service Manager

First Choice for Dependable Engine Performance