



AVIATION TECHNICAL BULLETIN

Champion Spark Plug Company

P. O. BOX 910, TOLEDO, OHIO 43601

October 2, 1968

ROUTE TO	
SERVICE MANAGER	
SALES MANAGER	
BULLETIN BOARD	

NO. 68-16

CONTROLLED
COPY

GAP SETTINGS FOR J43 & REJ38 SPARK PLUGS

The Champion J43 and REJ38 spark plugs have limited applications and are, shall we say, forgotten children in many ways. One of them is the electrode gap setting and/or opening.

Champion delivers these plugs with an .020 gap setting. Experience has proven that for optimum engine performance, the .020 setting is recommended.

This gap setting also applies when field reconditioning of these two plug types is performed.
