



AVIATION TECHNICAL BULLETIN

Champion Spark Plug Company

P. O. BOX 910, TOLEDO, OHIO 43601

July 1, 1969

NO. 69-8

ROUTE TO	
SERVICE MANAGER	
SALES MANAGER	
BULLETIN BOARD	

CONTROLLED
COPY

CRACKING INSULATOR CERAMICS?




FOUR-PRONG "N"
GROUND ELECTRODES



TWO-PRONG "E"
GROUND ELECTRODES

Two-Prong "E" and Four-Prong "N" Electrodes, both short- and long-reach, can be adjusted with the Champion CT-415 Gap Setting Tool as shown.



Setting One Gap at a Time
with CT-415 Gap Tool

TO AVOID FRACTURING THE INSULATOR CERAMIC ALWAYS REMOVE THE WIRE FEELER GAUGE WHILE ACTUALLY ADJUSTING THE GAP.
