



AVIATION TECHNICAL BULLETIN

Champion Spark Plug Company

P. O. BOX 910, TOLEDO, OHIO 43601

September 1, 1971

NO. 71-10

ROUTE TO	
SERVICE MANAGER	
SALES MANAGER	
BULLETIN BOARD	

CONTROLLED
COPY

PROPER TORQUING CAN ASSURE AGAINST OIL FILTER LEAKS

Always use a torque wrench and be sure the specified torque is used to install the filter.

If seepage does occur, the unit should be removed and all areas rechecked rather than additional torquing. This may only place additional strain on the gaskets and cause the gasket to fail.

Spare gasket kits (CFO-205) are available through your Champion supplier.
