



AVIATION TECHNICAL BULLETIN

Champion Spark Plug Company

P. O. BOX 910, TOLEDO, OHIO 43601

NO. 71-11

October 1, 1971

| ROUTE TO | |
|--------------------|--|
| SERVICE MANAGER | |
| SALES MANAGER | |
| BULLETIN BOARD | |

OIL FILTER ASSEMBLY NEEDS CLEANING, TOO.

Before installing the new filter element, be sure the gasket surface has been cleaned and is free of dirt deposits to assure proper sealing.

If the mounting plate is scratched or dented, this too may cause a serious oil leak.

Taking the time to clean and inspect the gasket surface area can eliminate a lot of grief for you and your customer.

Always check for oil leaks by starting and warming up the engine.

Take time to be sure!
