



AVIATION TECHNICAL BULLETIN

Champion Spark Plug Company

P. O. BOX 910, TOLEDO, OHIO 43601

ROUTE TO	
SERVICE MANAGER	
SALES MANAGER	
BULLETIN BOARD	

February 1, 1972

NO. 72-2

MURPHY'S LAW

CONTROLLED
COPY

"If an aircraft part can be installed incorrectly, someone will install it that way."



The result of a spark plug that was not properly seated or torqued.

This picture illustrates what happens when the spark plug has not been installed properly into the cylinder. Result -- engine fire.
