



AVIATION TECHNICAL BULLETIN

Champion Spark Plug Company

P. O. BOX 910, TOLEDO, OHIO 43601

September 15, 1977


NO. 77-5

ROUTE TO	
SERVICE MANAGER	
SALES MANAGER	
BULLETIN BOARD	

GET THE LEAD OUT - FASTER!

CONTROLLED
COPY

MECHANICS AND OPERATORS ARE FINDING, UPON REMOVING THE LOWER SPARK PLUGS IN HORIZONTAL OPPOSED ENGINES, THAT THE FIRING END CAVITIES OF THESE PLUGS ARE FULL OF LEAD OXIDE. THIS TYPE OF DEPOSIT IS EXTREMELY DIFFICULT TO REMOVE WHILE SERVICING, HOWEVER, CHAMPION'S MODEL 200 VIBRATOR CLEANER MAKES THE CLEANING OPERATION A SIMPLE AND EASY PROCEDURE.



SO, GET THE LEAD OUT! BUY A CHAMPION MODEL 200 CLEANER AND DISCOVER FOR YOURSELF JUST HOW EASY IT REALLY IS TO REMOVE THESE LEAD DEPOSITS!