



AVIATION TECHNICAL BULLETIN

Champion Spark Plug Company

P. O. BOX 910, TOLEDO, OHIO 43601

February 21, 1978

NO. 78-1

ROUTE TO	
SERVICE MANAGER	
SALES MANAGER	
BULLETIN BOARD	

**CONTROLLED
COPY**

FOLLOWING ARE THE CHAMPION/LYCOMING EQUIVALENT
OIL FILTER PART NUMBERS:

CH48111 = LW-13216

CH48104 = LW-13905

AVCO LYCOMING WILLIAMSPORT DIVISION RECENTLY RE-
LEASED THEIR SERVICE INSTRUCTION NO. 1319A WHICH
PERTAINS TO "ENGINE MOUNTED FULL-FLOW OIL FILTER".

FOLLOWING IS AN EXCERPT FROM THIS BULLETIN CON-
CERNING 100-HOUR OIL FILTER CHANGE INTERVALS:

"Operators of 0-235 series engines that incorporate full-flow filters may increase their oil and filter change time to 100-hour intervals. In addition, 0-320 series engines equipped with full-flow filters can also benefit from the 100-hour oil and filter change intervals by using the increased capacity spin-on oil filters P/N LW-13216 (long) or LW-13905 (long)."

WE SUGGEST YOU ADVISE YOUR CUSTOMERS OF THE CHAMPION
OIL FILTER APPLICATION PART NUMBERS.
