



AVIATION TECHNICAL BULLETIN

Champion Spark Plug Company

P. O. BOX 910, TOLEDO, OHIO 43601

ROUTE TO	
SERVICE MANAGER	
SALES MANAGER	
BULLETIN BOARD	

January 18, 1979

NO. 79-1

CONTROLLED
COPY

ABRASIVE COMPOUND USE

DUE TO THE SMALLER SIZE CLEANER BAG ASSEMBLY OF THE NEW CT-475AV CLEANER/TESTER, IT HAS BEEN NECESSARY TO CHANGE THE ABRASIVE "CHARGE" SIZE. ALTHOUGH THE COMPOUND IS THE SAME, USE OF THE WRONG QUANTITY COULD RESULT IN POOR CLEANING ACTION.

PART #533 IS FOR USE IN THE MODELS 2400, 800H, 800E, AND 700 UNITS AND CONTAINS 1 LB., 14 OZ. OF COMPOUND AND ONE #622 NOZZLE TIP.

PART #91893 IS FOR USE IN THE NEW CT-475AV AND CONTAINS 15 OZ. OF COMPOUND AND ONE #94023 (#622) NOZZLE TIP.

WHEN CHANGING ABRASIVE IN ANY OF THE UNITS, REMOVE ALL OLD ABRASIVE AND THE WORN NOZZLE TIP. INSTALL THE NEW TIP, THEN POUR THE ENTIRE "CHARGE" OF NEW ABRASIVE INTO THE CENTER (CLEANING SECTION) OF THE UNIT BY POURING IT THROUGH THE TOP OF THE UNIT.

ADHERENCE TO THE ABOVE REGARDING USE OF CORRECT QUANTITIES OF ABRASIVE WILL RESULT IN PROPER CLEANING AND TESTING OF ALL MASSIVE AND FINE-WIRE AVIATION SPARK PLUGS.

DAH:ch
