



AVIATION TECHNICAL BULLETIN

Champion Spark Plug Company

P. O. BOX 910, TOLEDO, OHIO 43601

September 15, 1982

NO. 82-6

ROUTE TO	
SERVICE MANAGER	
SALES MANAGER	
BULLETIN BOARD	

CT-475AV TROUBLE SHOOTING METHOD

TO OPEN AN OBSTRUCTED PICK UP TUBE IN THE CHAMPION CT-475AV CLEANER/TESTER, REMOVE THE RUBBER NOZZLE TIP AND FOLLOW THE BELOW PROCEDURE:

USING A COAT HANGAR, WELDING ROD, OR SIMILAR PIECE OF WIRE, GENTLY PROBE DOWN THE PICK UP TUBE TO CLEAR IT. EXCESSIVE FORCE COULD, HOWEVER, RESULT IN DAMAGE TO THE BAG OR PICK UP TUBE.

FORMER PRACTICE OF PLACING A FINGER OVER THE NOZZLE AND QUICKLY DEPRESSING THE ABRASIVE BLAST ON THE CHAMPION MODELS 800 AND 2400 CLEANERS HAS PROVED TO BE POTENTIALLY DAMAGING TO THE UPPER MANIFOLD ASSEMBLY IN THE CT-475AV BY CAUSING IT TO RUPTURE. WE THEREFORE SUGGEST ADHERENCE TO THE MANUFACTURER'S METHOD AS INDICATED ABOVE.

CONTACT YOUR CHAMPION ZONE SALES MANAGER IF THERE ARE ANY QUESTIONS REGARDING TROUBLE SHOOTING PROCEDURES ON THIS CLEANER/TESTER UNIT.

SRF/ch
