



# Aviation Technical Bulletin

**Route to:**SERVICE  
MANAGERSALES  
MANAGERBULLETIN  
BOARD

January, 1988

88-1

## #533 ABRASIVE REPLACED BY 91893

No. 91893 abrasive compound will replace #533 abrasive in all Champion spark plug cleaner units once existing inventory is exhausted. Cleaners formerly using the #533 abrasive will require two bags of 91893 to fully charge the unit. The chart below should be followed when replacing abrasive:

- 1) Use two bags of 91893 abrasive to fully charge Champion's 2400, 800H, 800E, and 700 cleaners.
- 2) Use one bag of 91893 to fully charge the CT475AV cleaner/tester.

Each bag of abrasive contains one #622 nozzle tip. Operators using two bags of abrasive should remember to remove and save the extra nozzle tip.

JTQ:c1