



Aviation Action Alert

Route to:SERVICE
MANAGERSALES
MANAGERBULLETIN
BOARD*Bringing Power to Flight*

December 1989

89-7

CHAMPION OIL FILTER RECALL

Champion is requesting the return of CH48108 and CH48109 spin-on filters manufactured during the period of September through December, 1988, on which the following date codes appear: (First three digits) 3J8, 4J8, 1K8, 2K8, 3K8, 4K8, 2L8, 1M8, 3M8.

Collapse of the internal element on filters with the above date codes can occur during start in cold weather if engine manufacturers' cold starting procedures are not strictly followed. This condition will cause the filter to stay in by-pass and prevent full filtration until changed.

All filters with the affected date codes should be returned to your Aviation Distributor for credit or replacement, at your option.

CH48108 & CH48109

1K8	3J8
2K8	4J8
3K8	1K8
1M8	4K8
	2L8
	3M8



We apologize for any inconvenience our recall may cause. Although your prompt cooperation in returning affected filters is appreciated, we have excellent inventory and anticipate no problems in supplying filters during the recall period.

Please do not hesitate to contact Champion or your Aviation Zone Sales Manager if you have any questions.

WLA:fcg

Champion Aviation Products: Your Blueprint for Performance