



Aviation Action Alert

Route to:

SERVICE
MANAGER

SALES
MANAGER

BULLETIN
BOARD

Bringing Power to Flight

February, 1989

89-1

TO: ALL OPERATORS OF GENERAL ELECTRIC CFM56-5 ENGINES

RE: IGNITER CHANGE
FROM: CH31772
TO: CH31806

SINCE PUBLICATION OF THE AV-12 AVIATION PRODUCTS CATALOG, OEM HAS CHANGED RECOMMENDATION OF THE IGNITER USED IN THE CFM56-5 ENGINE FROM CH31772 (T-4/9387M23P01) TO CH31806 (T4/1374M13P01).

THE CATALOG CHANGE WILL BE AS FOLLOWS:

PAGE 36

<u>CFM INTERNATIONAL</u>	<u>CHAMPION TYPE NO.</u>	<u>ENGINE MFR. PART NO.</u>	<u>AIRCRAFT MAKE</u>	<u>AIRCRAFT MODEL</u>
CFM56-5	CH31806	1374M13P01	Airbus Industries	A320

WLA:c1